DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-003536

Address: 333 Burma Road **Date Inspected:** 08-Aug-2008

City: Oakland, CA 94607

OSM Arrival Time: 630 **Project Name:** SAS Superstructure **OSM Departure Time:** 1530 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: CWI Present: Yes n/a No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A Yes N/A **Electrode to specification:** No Weld Procedures Followed: Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes No N/A **Approved Drawings:** Yes No **Approved WPS:** Yes No N/A **Delayed / Cancelled:**

34-0006 **Bridge No: Component:** OBG/Tower

Summary of Items Observed:

Caltrans Quality Assurance (QA) Inspector Sherri Brannon arrived on site at the Zhenhua Port Machinery Company (ZPMC) facility at Changxing Island, in Shanghai, China to periodically monitor welding and Quality Control (QC) functions. While on site the QA Inspector observed and/or discovered the following.

Material Test Reports:

Based on random review Quality Assurance (QA) Inspector Brannon reviewed Material Test Reports (MTR's) plate list batch 166, batch 167, batch 168, batch 169, batch 170, batch 171, batch 172, batch 173, batch 174, batch 175, batch 176, batch 177 and batch 178, for material received in the ZPMC yard. QA Inspector Brannon checked MTR's for material designation, heat numbers, weights, carbon equivalent, sulfur content, fine grain particles, through-thickness, ultrasonic testing and reduction of area. For additional information see Caltrans Review of Contractor's Transmittal TC-20 generated on this date.

Summary of Conversations:

No relevant conversations to report.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Ady Velasco 13816942685, who represents the Office of Structural Materials for your project.

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

Inspected By:	Brannon, Sherri	Quality Assurance Inspector
Reviewed By:	Lanz,Joe	QA Reviewer